

MINI M

Vehicle information




Make:	MINI	License:	GM912MP
Gearbox:		Body color:	
Model:	M	VIN:	WMW21BS0303R16942
Fuel type:	Plug-in hybrid	Power:	
Version:	MINI Countryman	First registration	03/03/2023
Mileage:	56411 km	N° of doors:	

Damage summary

Front	1
Left	2
Right	1
Roof & others	1

Commercial pictures





Options according to the inspector

No option checks information found

Damages

Bodywork

- Paint measurement
- Acceptable
- Roof & others



Bonnet

- Scratch(es)
- Polish
- Front



Door trim RR

Scratch(es)
Replace
Right



Outside rear-view mirror housing L

Scratch(es)
Acceptable
Left



Wing trim FL

Scratch(es)
Replace
Left



Tyres			
	Front Left		
	Summer		
	225/55/17/101/W		
	Nexen		
	6.0 mm		
	Front Right		
	Summer		
	225/55/17/101/W		
	Nexen		
	6.4 mm		
	Rear Left		
	Summer		
	225/55/17/101/W		
	Yokohama		
	5.0 mm		
	Rear Right		
	Summer		
	225/55/17/101/W		
	Yokohama		
	4.1 mm		

Checks			
Category	Passenger Car	Engine functioning	Yes
Jack	N/A	Luggage cover	Yes
Number head rests	5	Number keys remote	2
Number of keys total	2	Registration Certificate	Yes
Registration Certificate	Original		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.